
DATE:	16 Oct. 196	25X1A   3 25X1A	S E C I HF-K-8275 1		3 4 5 6	D SI AI	TECH FA DOSA DOSA SOSA	11 12 13 14		
FROM	DIRECTOR				6		o/ COR	15		
CONF	DIRECTOR		d	octive!	P. T. B. C. B.		DEFERRED	1	ORITY	BHITIALS
INFO :	0=A 1-	-15	Cal		MOZMO	X	ROUTINE		ATIONAL EDIATE	INITIALS
25X1A ======	25X1A				**********	Be one-demoderate		hiji	<b>7244</b> :	<b>16</b>
TO CX	CART		FQ			(	CITE			
	FIREWEL IN	STRUCTED TO S	HIP 14 EA CY	Linders, high p	RES	SUR	E (2000 P	SI)		25X1

END OF MESSAGE

25X1A



AT \$4 read house		ROUTING	_ ₽3
A T this reason are		HOUTING.	<b>₹3</b>
Altinatama	*	HRC.	23
	* # \$ \$	74	
	* *		1
			<del>                                     </del>
en/osa			+
	3 3		+
~~~~ <u></u>	<b></b>		<del> </del>
	* *		+
			-
			_
elease 2002/07/30 : 0		)285R000300	18
ANSWERED	NO REPLY		
	The second secon	elease 2002/07/30 : CIA-RDP75B00	elease 2002/07/30 : CIA-RDP75B00285R000300

25X1A

Approved For Release 2002/07/30: CIA-RDP75B00285R000300180006-4

OSA-5678-63

4 November

Dear A1:

Per our telecon it is decided that the neck seal in the full pressure suit is not desirable. All suits with the neck seal should be reconverted to the face seal and any present work to install the neck seal should be discontinued.

Request you modify suit by removing the 25X1A vent air ring at the wrists and boot tops. When the suit for 1045 is returned please modify it likewise. We will wait for comments from the pilots on this mod before changing any other suits.

Sincerely,

25X1A